



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
WAYLAND ROAD	o/s 106	TR: Felling	Extensive f/w damage, kerb displacement, stem encroaching c/w	Prunus serrulata	Plant in new 800 pit in same position	Crataegus laevigata 'Paul's Sc
WAYLAND ROAD	o/s 100	TR: Felling	Extensive f/w damage, kerb displacement	Prunus x yedoensis	Plant in new 800 pit in same position	Crataegus laevigata 'Paul's Sc
WAYLAND ROAD	o/s 98	TR: Felling	F/w mounded and poor structural condition - multiple weak unions at crown break	Prunus x yedoensis	Plant in new 800 pit in same position	Crataegus laevigata 'Paul's Sc
WAYLAND ROAD	o/s 54	TR: Felling	Kerbs displaced by buttress roots - unable to reset without root damage, also weak unions at crown break	Prunus x yedoensis	Plant in new 800 pit o/s 54/56	Crataegus laevigata 'Paul's Sc
WAYLAND ROAD	o/s 54	TR: Felling	Kerbs displaced by buttress roots - unable to reset without root damage, also weak unions at crown break	Prunus x yedoensis	Plant in new 800 pit in same position	Crataegus laevigata 'Paul's Sc